COPY

Submitted @ 10/24/16 Public Hearing

Town of Grafton
NE Hazard Tree Mitigation Program
Scenic Road Hazard Tree Removal List
Circuit # 304W1





ID	Street	#	Loc	Pl	DBH	Species	Defects	Work
99	Wesson	Lot	AF	2	26	Pine	Lean, weight to line, dieback, thin crown	Remove





ID	Street	#	Loc	Pl	DBH	Species	Defects	Work
99	Wesson	Lot	AF	2-3	22	Pine	Lean , weight to line, dieback, thin crown	Remove



ID	Street	#	Loc	Pl	DBH	Species	Defects	Work
100	Wesson	5	AF	2-3	12	Oak	Lean, weight to line, heavy dieback	Remove



ID	Street	#	Loc	Pl	DBH	Species	Defects	Work
100	Wesson	5	AF	2-3	8	Birch	Lean, weight to line, heavy dieback	Remove

ID	Street	#	Loc	Pl	DBH	Species	Defects	Work
100	Wesson	5	AF	2-3	8	Birch	Lean, weight to line, heavy dieback	Remove

ID	Street	#	Loc	Pl	DBH	Species	Defects	Work
100	Wesson	5	AF	3-4	30	Oak	One lead lean and weight over line, Irregular growth, dieback, wound 3 ft. up trunk with rot	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
101	Wesson	7	AF	4	34	Oak	Heavy dieback, no root flare, decline	Remove

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
102	Wesson	9	AF	4 -5	24	Red Maple	Lean, weight to line, dieback, rot in old branch scars, no root flare	Remove

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
104	Wesson	Lot		9-10	24	Oak	Trim 8 in. dead lead going straight up	Trim

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
104	Wesson	Lot	AF	9	34	Norway Maple	Heavy dieback, cavities with rot Large amount of bark missing	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
106	Wesson	26		12-13	24	Cherry	Heavy dieback, poor structure, weak species	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
106	Wesson	26		12-13	12	Cherry	Heavy dieback, poor structure, weak species	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
106	Wesson	26		12-13	20	Cherry	Heavy dieback, poor structure, weak species	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
110	Wesson	41	AF	17-17.5	23	Oak	Lean, weight to line, poor structure, dieback	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
111	Wesson	43	AF	19	28	Ash	More than 50% dead; EAB susceptible	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
114	Wesson	66	AF	26-27	32	Oak	Trim branches over lines	Trim

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
114	Wesson	66	AF	26-27	28	Oak	Trim branches over lines	Trim



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
117	Wesson	74		29-30	5	Red Maple	Dead	Remove

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
119	Willard St	lot	AF	28-1	42	Oak	Trim as many dead branches as possible	Trim

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
120	Willard St	lot	AF	28-1	13	Ash	More than 60% dead; EAB susceptible	Remove

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
120	Willard St	lot	AF	28-1	11	Ash	More than 60% dead; EAB susceptible	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
120	Willard St	lot	AF	28-1	20	Ash	More than 70% dead; EAB susceptible	Remove

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
121	Willard St	2		28-1	56	Oak	Trim dead material over lines	Trim

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
122	Willard St	4	AP	2	26	Locust	Minimal crown, dieback, proximity	Remove

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
123	Willard St	27	AF	6-7	26	Oak	Trim dead wood toward lines	Trim

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
123	Willard St	Lot		6-7	26	Pine	Weight over lines, very little crown, heavy dieback	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
125	Willard St	Lot	AP	8	28	Pine	Weight over lines, thin crown trunk leans to pole, trunk 3 ft. from pole	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
125	Willard St	Lot	AF	9-10	38	Oak	More than 50% dead, very little crown, wounds on trunk, insects present	Remove



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
126	Willard St	Lot		11-12	25	Hickory	Trim dead material over line	Trim



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
127	Willard St	Lot		11-12	20	Oak	Trim dead material over line	Trim

ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
127	Willard St	Lot		13-14	45	Oak	Trim dead material over line	Trim



ID	Street	#	Loc	Pole#	DBH	Species	Defects	Work
127	Willard St	Lot		15-16	26	Hickory	More than 70% dead	Remove