

1. Balance
The back of the expansion is asymmetric to the front so it does not overpower the historic building. While this aesthetic may not be pleasing to everyone, it is functional to the design.
2. Eliminate doors
We are required to provide access to emergency responders and egress from the stairwell. However, we will review the placement of these 2 exterior doors.
3. Sloped metal roof. Green roof could be used on existing bldg & new addition.
The nearly 100-year old slate is holding up remarkably well. If it's not broke, we don't want to spend money unnecessarily to "fix" it.
4. Patio – partially cover with trellis
We will pass this suggestion to the architect.
5. Second media projector
The plans include a second media projector for the large meeting room so if it's divided, both sides have projection capability.
6. Does sprinkler room need an exit door? Are there components that could be accessible from exterior i.e. hydrant?
Possibly, will bring to architect.
7. [Move] Staff Room & Break Room [to where Children's office space is]
That would necessitate putting the children's staff offices on the upper level, removing the staff from the Children's Room, and moving the Down Under Storage to the upper level, requiring donors and volunteers to truck donations up and down the elevator.
8. Shelving/Kid Sink
Both components are outlined in building program, and were identified by the Children's Librarian as essential.